



**ADDENDUM #1 for:**

**Village of Oak Park Fire Sprinkler System Testing Services**

**Bid Number: 23-135**

**Issuance Date: 11/1/2023**

**ADDENDUM Issue Date: 11/1/23**

The following is an Addendum to the Request for Proposals (RFP) for the

**Village of Oak Park Fire Sprinkler System Testing Services**

The RFP is to include the following additional SCOPE OF WORK added at the end of the original SCOPE OF WORK SECTION:


**SECTION III**

**SCOPE OF WORK**

**Additional Scope of Work:**

Install a new dual check-valve on the sprinkler system at the main fire station located at 100 N. Euclid.

Below is water entrance drawing from 1981. Sprinkler company shall inspect/verify actual existing conditions.



**DIAGRAM - WATER SERVICE ENTRANCE**

This is a link <https://www.watts.com/products/plumbing-flow-control-solutions/backflow-preventers/ames-deringer/deringer-2020g> to the company that makes this double check-valve 'Derringer' model line. Sprinkler company shall review what model would be best for this building based on the existing inlet size, existing pressure, recommended GPM, code requirements, etc.

There will be additional work required to remove the existing single check-valve, and the existing pipes will likely need to be shortened or lengthened on either side to accommodate the different size new dual check-valve. The system will need to be drained in order to perform this work. Work shall take place when sprinkler system testing for this location is scheduled (to avoid having to drain the entire system twice).

The RFP is to include the following revised Proposal Form:

**SECTION IV**

**PROPOSAL FORM (Pricing)**

The undersigned proposes to furnish all labor and materials required to complete the Work in accordance with the attached specifications and at the prices indicated below.

Total Annual Cost for Public Works Center, 201 South Blvd: \$ \_\_\_\_\_

Total Annual Cost for Village Hall, 123 Madison: \$ \_\_\_\_\_

Total Annual Cost for Main Fire Station, 100 N. Euclid: \$ \_\_\_\_\_

Total Annual Cost for North Fire Station, 212 Augusta: \$ \_\_\_\_\_

Total Annual Cost for South Fire Station, 900 S. East Ave: \$ \_\_\_\_\_

Total Annual Cost for Holley Court Parking Garage, 1125 Ontario: \$ \_\_\_\_\_

Total Annual Cost for Avenue Parking Garage, 720 North Blvd: \$ \_\_\_\_\_

Total Annual Cost for OPRF Parking Garage, 137 N. Scoville: \$ \_\_\_\_\_

Alternates:

Alternate Bid #01: Repair Village Hall deficiencies (based on the Inspection and Testing Report as submitted by Assurant Fire Protection dated 09/06/2023):

\$ \_\_\_\_\_

Alternate Bid #02: Install New dual check-valve on the sprinkler system at the main fire station:

\$ \_\_\_\_\_